



APUs



ATI performs all major repairs to the GTCP 36 Series and T-62T Family of APUs

We have developed FAA-approved repairs that provide continued operation of most high-end APU components, allowing us to be very competitive. We provide options: Repaired vs. New. Since repairs are significantly more cost effective than replacing existing hardware with new parts, our “repair rather than replace” philosophy saves money and we pass that savings back to you, our customer. ATI backs up all APU work and repairs with our full one (1) year warranty on parts and labor.

Specialized Services Include:

- FAA and EASA Certified
- Facility Locations in the United States and United Kingdom
- Turbine/Compressor Rotor Replacement
- All APU Inspections/Service Bulletin Compliance
- State-of-the-Art APU Test Cell - Full Data Acquisition System
- Authorized Support for Honeywell Maintenance Service Plan (MSP)
- No-charge T-62T Loaner APUs Based on Availability
- 24/7 After-Hours Technical Support (Ed Martin - 314.565.0805 or Jason Carles - 314.565.3109)
- 24/7 After-Hours Parts Support (636.532.2674)
- T-62T-40C Series APU Training - FAA-Approved 2 Day Course
- ISO 9001:2000 QMS Certified
- U.K. Office Contact - Gary Simpson (+44 (0) 1425 482360)

From turbine rotor replacement to after-hour technical support, ATI is your corporate and regional jet APU specialists.



FAA Certified Repair Station #OTUR438L
EASA.145.4216



836 Texas Court
O'Fallon, MO 63366

636.532.2674
www.avmats.com
ISO 9001:2000